

Preliminary Incident Details		
Operation	Climax	
Date / Time	July 5, 2023 / 5:18 a.m.	
Туре	Property Damage	
Summary	A fully loaded haul truck was traveling downhill on a haul road and failed to make a turn. The truck went through two berms before coming to a stop against the face of a hill near a steep drop off. The contractor driver was assessed at the clinic and released without any injuries.	
Fatal Risk	Vehicle Collision or Rollover	
Risk Category	Monitor	
Pre / Post Rating	Significant (3) Possible (2)	
Findings / Missing Controls	Failure to engage downhill speed control	
Applicable Policies / Procedures	Interaction with Heavy Mobile Equipment (2.6)	
Employee Condition	No injury	
Contact	Tanner Thetford, Superintendent-Mine Operations	



Final location of haul truck



Causal Factors	I		
 Haul truck operator traveled at 15 mph down a 10% grade ramp (no grade % or speed signage exists) with a 240-ton load without activating the dynamic braking speed control, as suggested by manufacturer Haul truck operator feathered the dynamic brakes, which was an ineffective action to keep the haul truck (Liebherr T264) within the braking capabilities Haul truck operator did not use the service brake (secondary) to slow the truck down when the dynamic braking system (primary) was ineffective 		Operating Con Fit For Work a Vehicle Preop • Have I condu	
Action Items	Hierarchy of Controls	the vehicle)?	
Install grade % and speed signage as a visual cue for haul truck drivers on downhill ramps	Administrative	Access Contro Segregation –	
Retrain operators (task training) on use of Liebherr T264 dynamic braking application, downhill speed control and service brake application	Administrative	Signage and D Road Design A	
Set the adjustable speed limit (brake governor) on all Liebherr T264 trucks on-site. Climax and Thiess will determine the proper speed	Engineering		
Additional Learnings / Opportunitie) S		
 Climax and Thiess health and safety personnel will have ongoing converge pre-job expectations Thiess supervisors will conduct routine checks to verify operators are we Thiess will assign a ReadiWatch to employees to meet its fatigue manage Climax has communicated DSS eyewear requirements to supervisors 	aring the proper PPE		

atal Risk Management Controls

petency – Sufficient

d Fatigue Management - Sufficient

rational Inspection – Insufficient

cted a pre-operational inspection prior to use (specific for

unication System – Sufficient

- Sufficient

ufficient

emarcation – Insufficient

nd Maintenance – Sufficient