Safford Contractor Monthly Meeting

February 12, 2025







fcx.com

FREEPORT FOREMOST IN COPPER

All Operating Sites

Working Together Saves Lives!



If you don't know, ask. Working with people is far better than working against them — always bring together all the people and information available to you!

PFE and Actionable Incidents







Release of Energy

Actionable Event: Haul Truck Dump Body Fell onto Frame

ID # 2025-01 Event ID # 20022669

| | Preliminary Incident Details | | | | | | |
|-------------------------------------|--|--|--|--|--|--|--|
| Operation | Chino | | | | | | |
| Date / Time | January 19, 2025 / 1 p.m. | | | | | | |
| Event Type | Property Damage | | | | | | |
| Summary | Two contractor mechanics were replacing a haul truck engine and had also replaced all the hydraulic lines. After the engine swap, Mechanic 1 started the haul truck from the cab while Mechanic 2 went underneath to remove the retaining cable from the tow point and check the hydraulic tank fluid levels. Mechanic 1 pressed the switch to lower the dump body before building pressure on the bed hydraulic cylinders. Without the retaining cable and no pressure in the cylinders, the dump body fell freely onto the frame rails, breaking two cab windows and causing mud to fall near Mechanic 2. | | | | | | |
| Risk Category | Actionable – Significant (3) Likely (3) | | | | | | |
| Findings / Missing Controls | The retaining cable was removed prematurely. The hydraulic cylinders were not pressurized when the dump body was lowered. | | | | | | |
| Applicable Policies / Procedures | <u>FCX-HS04 Control of Hazardous Energy Policy</u> | | | | | | |
| Employee Condition | No injuries were reported. | | | | | | |
| Contact | Jim Cook, Manager-Health and Safety | | | | | | |



Photos / Links

The retaining cable attached from truck bed to haul truck frame

Mechanic 1 – inside truck cab

Mechanic 2 – approx. 5 ft. from hydraulic tank



Position of mechanics at time of incident



Actionable Event: Shovel Cable and Mat Caught on Service Truck



| Preliminary Incident Details | | | | | | | |
|---|--|--|--|--|--|--|--|
| Operation | Sierrita | | | | | | |
| Date / Time | January 22, 2025 / 6:45 a.m. | | | | | | |
| Event Type | Property Damage | | | | | | |
| Summary | As a service truck was turning into a drill corral entrance, the ri rear outrigger snagged a 7,200-volt shovel cable and crossove mat. Unaware of this, the operator continued driving. About 720 feet from the corral entrance, the cable contacted a portable restroom trailer. The cable broke at a section that had been previously patched, causing an arc flash. The truck finally came a stop 360 feet beyond the point of the cable failure. | | | | | | |
| Risk Category | Actionable – Significant (3) Likely (3) | | | | | | |
| Findings / Missing Controls | The crossover mat was missing bolts and in poor condition leaving minimal space between it and the outrigger. | | | | | | |
| Applicable Policies / Procedures · FCX-HS03 Electrical Safety Policy | | | | | | | |
| Employee Condition No reported injuries. | | | | | | | |
| Contact Cara Forbregd, Manager-Health and Safety Allen Kinney, Superintendent-Mine Operations | | | | | | | |

Photos / Links



Service truck with cable and mat caught on the outrigger.



Broken cable following contact with portable restroom trailer.



Condition of the crossover mat after contact with truck.



Cable and crossover mat before contact with truck.



ID # 2025-03 Event ID # 20022796

| Preliminary Incident Details | | | | | | |
|-------------------------------------|---|--|--|--|--|--|
| Operation | Morenci | | | | | |
| Date / Time | January 25, 2025 / 5:23 p.m. | | | | | |
| Event Type | Near Miss | | | | | |
| Summary | Ground personnel were in the final stages of clearing the blasting area. All holes had been tied-in, and the blasting crew was in the process of stringing out the shot. During this process, one hole self- detonated. The blasting crew made a radio announcement to clear all personnel from the area. At the time of incident, the blasting pattern was not connected to the blasting box. | | | | | |
| Risk Category | Actionable – Significant (3) Likely (3) | | | | | |
| Findings / Missing Controls | Human behavior did not contribute to this event, and all operating procedures were followed. The probable cause is ground reactivity, which has been mitigated by using a blasting inhibitor in site blasting operations. | | | | | |
| Applicable Policies / Procedures | FCX-15 Surface Blasting Policy | | | | | |
| Employee Condition | No reported injuries. | | | | | |
| Contact | Belen Lawrence, Manager-Health and Safety Kudir Kudadiri, Manager-Fragmentation and Mine Development | | | | | |



Unplanned hole ignition.



Potential Fatal Event: Failed Converter Guard

FREEPORT-MCMORAN

| | Preliminary Incident Details | | | | | |
|-------------------------------------|--|--|--|--|--|--|
| Operation | Miami | | | | | |
| Date / Time | January 26, 2025 / 7:30 p.m. | | | | | |
| Event Type | Near Miss | | | | | |
| Summary | An employee was tightening bolts on the air guns of a converter. In this area, guards are in place to cover holes when the converter is rolled down and handrails are removed. The employee had one foot on the hole guard when its weld failed. This caused the employee to fall forward, but they managed to catch themselves before falling through the opening. The potential fall distance was about 14.5 feet (4.5 meters). | | | | | |
| Risk Category | Actionable – Significant (3) Likely (3) | | | | | |
| Findings / Missing Controls | The converter hole guards are not designed to support personnel, but this is not widely understood. The guards are meant to protect against falling objects between the floor and the converter. Employees refer to the guard as a "platform," leading to confusion about how it should be used. Proper weld procedures were not followed during installation, resulting in poor-quality welds. Preventative maintenance checks do not include weld inspections. | | | | | |
| Applicable Policies / Procedures | <u>FCX-HS02 Working at Heights</u> | | | | | |
| Employee Condition | No reported injuries | | | | | |
| Contact | Justin Taylor, Manager-Health and Safety | | | | | |



49"

Photos / Links

32"

Broken guard welds

A view looking down through the open hole after guard failure

MSHA Daily Fatality Report 2021-2025 (as of Feb 11th)

THE VALUE OF COPPER



Fatalities chargeable to the Mining Industry


| | 200 | 24 | 20 | 22 | 2022 | | 2024 | | 2025 | |
|--------------------------------|-----|----|----|----|------|------|------|----|------|---|
| Accident Classifications | 20 | 21 | 20 | ZZ | 20 | 2023 | | Z4 | 2025 | |
| | UG | S | UG | S | UG | S | UG | S | UG | S |
| ELECTRICAL | 0 | 0 | 0 | 0 | 0 | 3 | 0 | 0 | 0 | 0 |
| EXP VESSELS UNDER PRESSURE | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| EXP & BREAKING AGENTS | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| FALL/SLIDE MATERIAL | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 2 |
| FALL OF FACE/RIB/HIGHWALL | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| FALL OF ROOF OR BACK | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| FIRE | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| HANDLING MATERIAL | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| HAND TOOLS | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| NONPOWERED HAULAGE | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| POWERED HAULAGE | 1 | 2 | 0 | 2 | 0 | 1 | 0 | 2 | 1 | 1 |
| HOISTING | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| IGNITION/EXPLOSION OF GAS/DUST | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| INUNDATION | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| MACHINERY | 0 | 1 | 1 | 0 | 1 | 1 | 0 | 0 | 0 | 1 |
| SLIP/FALL OF PERSON | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 |
| STEP/KNEEL ON OBJECT | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| STRIKING OR BUMPING | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| OTHER | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| YEAR TO DATE TOTALS | 1 | 3 | 2 | 4 | 1 | 6 | 0 | 2 | 1 | 4 |
| COMBINED YEAR TO DATE TOTALS | 4 | 4 | 6 | | 7 | | 2 | | : | 5 |
| END OF YEAR TOTAL | 3 | 8 | 3 | 0 | 4 | 0 | 28 | | | |

UG- Underground Mines S – Surface Mines

- 5 Fatalities for 2025
 - 2 Powered Haulage
 - 1 Machinery
 - 1 Highwall Failure
 - 1 Falling Material

Safford Site HS Info





Safford MAYDAY SOP



FREEPORT-MCMoRAN

| | SOP # | S | | | | |
|------------------------------------|------------------------|----|--------|--|--|--|
| | ORIGINAL DATE | 2/ | | | | |
| STANDARD OPERATING PROCEDURE (SOP) | REVISION DATE | | | | | |
| Safford Operations | DIEK | | HIGH | | | |
| | RISK CLASSIFICATION | | MEDIUM | | | |
| | | Х | LOW | | | |
| Initiate an Emergency (MAYDAY) | | | | | | |

I. PURPOSE

All employees know and understand how to initiate an Emergency (MAYDAY). Following these procedures will help ensure the safest and most efficient emergency response for all employees, contractors, and visitors on the Freeport-McMoRan Safford property.

- MAYDAY, MAYDAY, MAYDAY on the primary channel in the area of the emergency.
- Press the ORANGE/P4 button on the radio and wait for console operator to answer the call.
- 3. Call the EMERGENCY NUMBER 928-792-5800.

NOTE: When a Mayday is called at any location, maintain radio silence to give access to emergency services. All traffic in all areas is to stop until the Mayday is cleared. At times specific areas of the property may be cleared sooner, this is to be done by Supervision receiving the approval from the on-scene safety professional. All Confined Space entries are suspended until an all clear is given AND Rescue is back in service and available to respond.

FMSO Initiate An Emergency(Mayday) SOP.docx

Safford January Reportable Incidents



| Incident # | Date | Туре | Division | Description | Mechanism | Body Part |
|---------------|-----------|----------------------|---------------------|---|----------------------|-----------|
| 1 | 1/10/2025 | | Mine Maintenance | Lube truck rear brakes caught fire, and employee was trying to put out flames with fire extinguisher when the rear tire blew. | Contact with | Head/Neck |
| 2 | 1/21/2025 | Medical Treatment | RAM Enterprises | | Rubbed or Abraded | Eye |
| 3 | 1/29/2025 | Restricted Duty | Hydromet | While lifting propane gun, employee felt pain. | Sprain/Strain | Torso |
| 4 | 1/29/2025 | Restricted Duty | Mine Operations | Haul truck driver was jarred in truck when it struck a mine haul road berm. | Collision | Back |

4 First Aids (Oil in eye, copper blank to leg, debris in eye, rolled rock onto finger)

Safford Safety Performance


THE VALUE OF COPPER



Reportable Incidents/Rate January: 4 / 1.98

> 1Q24 Incidents/Rate: 4 / 1.98

- YTD Incidents/Rate: 4 / 1.98
 2025 TRIR Target: 1.19
- Contractors YTD: 1 / 1.63



Incident trends 2024 Week to Week



THE VALUE OF COPPER





[■]Week # & NM ■Week # & PD ■Week # & FA ■Week # & MT ■Week # & RD ■Week # & LT

Monthly Incident/Hours reporting



FOREMOST IN COPPER

FREEPOR

- Due the 5th day of the month (or sooner) for the following month
- Be sure to send to Dolli Herrera (<u>dherrera3@fmi.com</u>)
 - You may remove Marjorie Ogas and Cynthia Lacey-Dalton

| Contractor Company Name | Numbe r of First Aid Inciden ts | Number of Medical Treatment Injuries (not lost time or restricted | Number of Lost time/Restrict ed Duty incidents | Number of lost/restricte d workdays | Number of Occupatio nal Illnesses | rof | Numbe r of Proper ty Damag e | Numbe r of Near Miss | Numbe r of Fire Inciden ts | Number of Environmen tal Releases | MSHA Regulate d Project Hours ¥orked | OSHA Regulat ed Project Hours ¥orked | Total work hours | Projec t TRIR | Status of Project H&S Goals, as applicabl e |
|----------------------------|--|---|--|---|--|-----|---|-------------------------------|--|--|---|---|------------------------|------------------|--|
| January | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| February | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| March | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| April | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| May | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| June | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| July | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| August | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| September | | | | | | | | | | | | | 0.00 | #DIV/0! | |
| October | | | | <u> </u> | | | | | | | | | | | |
| November | | | | | | | | | | | | | | | |
| December | | | | | ailv I | Mar | nno | MA | r R | epor | | | | | |
| Cumulative Year-to-Da | 0 | 0 | 0 | | any i | nai | ipo | we | | cpon | | | | | |
| | | Number of | | _ | | | | | | | | | | | |

 Just a reminder that if you are reporting TRIR hours you should have turned in a Daily Manpower Report for the days that you are onsite. This report is to be emailed to Alicia Aranda / <u>aaranda1@fmi.com</u> by 10am each day. **Personal Monitor - Rescue**







- If personal monitors are needed, they can be checked out daily at **Site 3 Rescue Trailer**
- Sign out and **Badge** is required to use these monitors for the day
- Badge will be returned at end of day or end of job when monitor is returned to Site 3



fcx.com

Global Supply Chain - Safford




All Operating Sites

Grievance Mechanisms

FREEPORT FOREMOST IN COPPER

FREEPORT-MCMORAN PRINCIPLES OF BUSINESS CONDUCT **SPEAK** UP **IF SOMETHING** DOESN'T FEEL RIGHT REPORT STRENGTH IN VALUES SAFETY RESPECT INTEGRITY manager or local HF EXCELLENCE COMMITMENT Scan QR cod to report a concern onlin



PLUS:

- Compliance with legal judgements
- Participation in third party non-judicial grievance mechanisms (OECD National Contact Points, Copper/Moly Mark Grievance Mechanism, etc.)

Grievance Mechanisms



Ensure to do both Panel 1 & Panel 2

GSC will finalize with GM approval

After GM approval is received and profiles finalized - EID's will be forwarded to you so that you may schedule training. Headshots / MSHA docs will be needed for badges. Badges are for employees who will be onsite for 2 weeks or more.

All Sub-contractors must be in ISN as well.

Any questions reach out to Alicia Aranda


(928)651-2832 / aaranda1@fmi.com



Environmental **Monthly Bulletin**







2024 SPCC spill Stats – Feb 2025

ENVIRONMENTAL MONTHLY BULLETIN February 2025

2024 Petroleum Spill Stats

Safford's Spill Prevention, Control, & Countermeasure Plan (SPCC) requires tracking and reporting of petroleum spills.

When Should I Report a Spill?

MYTH: Only report a spill if it is a release > 5 gallons

FACT: Report all spills outside of normal process conditions

Tips to avoid Petroleum Spills:

-Ensure containers are closed and secure
 -Have controls in place such as secondary containments and spill kits

 -Petroleum containers or tanks that contain 55 gallons
 or more require secondary containment
 -Secondary containments can be constructed from concrete,
 metal, plastic, or an earthen berm, and must hold 110%
 of the single largest container/tank inside the containment
 -Remove rainwater, spills, trash, and debris from containments

Submit an MOC when moving, removing, or adding containers, storage areas, and tanks.

THE VALUE OF COPPER

| 2024 Petroleum Spills | | | | |
|-----------------------|------------------|------|--|--|
| Month | Number of Spills | Gal | | |
| Jan | 5 | 395 | | |
| Feb | 3 | 72 | | |
| March | 3 | 1416 | | |
| April | 3 | 100 | | |
| May | 3 | 550 | | |
| June | 1 | 1 | | |
| July | 2 | 104 | | |
| Aug | 2 | 50 | | |
| Sept | 6 | 305 | | |
| Oct | 4 | 566 | | |
| Nov | 3 | 101 | | |
| Dec | 6 | 819 | | |
| Total: | 41 | 4479 | | |

| Total Petroleum Spills by Year | | | | | | |
|--------------------------------|-------|--|--|--|--|--|
| Year | Total | | | | | |
| 2024 | 41 | | | | | |
| 2023 | 21 | | | | | |
| 2022 | 51 | | | | | |
| 2021 | 40 | | | | | |

* FMSI lost approximately \$20,000.00 from spills of petroleum product in 2024.

Revision Date: February 2025


Intranet-posted document is the controlled copy. Verify printed document is still current prior to use.

FREEPORT

FOREMOST IN COPPER

Recent MSHA Inspection Findings -Morenci






Top Citation Grouping

FREEPORT FOREMOST IN COPPER

- Electrical Illumination, broken conduit, exposed wires, boxes not labeled, clearance in front of electrical boxes, missing knockouts
- Housekeeping Material in walkways, footprints in mud, built up dirt/debris
- Machinery & Equipment Cracked windows, missing bolts, broken handrail welds, homemade tools, guarding not secured, parking brake not set
- Fire Hazards Annual fire suppression inspections, used oil accumulation, oily rags disposal, BO fire extinguishers
- General Requirements Eye wash stations, dismounting equipment face forward

Fatal Risk Policy Review







February – Electrical FRM

----- FKEEPUKI-MCMUNAN



Health and Safety FCX-HS03 | Release 08/2019 | Version 1.1

POTENTIAL FATAL RISKS

Exposure to Electrical Hazards

CRITICAL CONTROLS

- Access Control
- Barriers and Segregation
- Electrical PPE
- Energized Electrical Work Permit Execution
- Energy Isolation/LOTOTO
- Engineering Controls

ELECTRICALLY QUALIFIED INDIVIDUAL

Only Electrically Qualified Individuals will perform de-energizing process to bring equipment to electrically safe work condition.

- An Electrically Qualified Individual:
- Has demonstrated skills and knowledge related to the construction and operation of electrical

POLICY

This policy intends to protect employees and contractors from the hazards of work around electrical installations and equipment.

- 1. Manage and reduce arc flash levels to the lowest possible.
- 2. Reduce exposure to electrical shock.
- 3. Provide protection to personnel when electrical work is performed.
- 4. Maintain electrical equipment and installations as safe and serviceable

ACTIONS TO STAY SAFE

- Electrical risk assessment is required before starting the work.
- Review SOPs for specific task before starting electrical work.
- Equipment must be de-energized except under exceptional conditions or trouble shooting.

ELECTRICALLY SAFE WORKING CONDITION

A state in which an electrical conductor or circuit part has been disconnected from energized parts, locked/tagged in accordance with established standards, tested to verify the absence of voltage, and, if possible, temporarily grounded for personnel protection.

Procedures to De-energize Electrical Equipment must include:

1. Determine all possible sources of electrical supply to the specific equipment. This may include: drawings, diagrams, and identification tags.

- Electrically Qualified
- Proper Labeling
- Distance from Over head Powerlines
- Requirements for Energized Work



GENERAL INFORMATION

 Anytime work is performed on electrical equipment and circuits, every effort must be made to de-energize the power in order to perform the necessary tasks. However, there are times when de-energizing the circuit is not possible. In these cases, appropriate justifications are required and must follow the processes and procedures defined in this Technical Supplement.

- When working within the restricted approach boundary or the arc flash boundary of exposed energized electrical conductors or circuit parts that are not placed in an electrically safe work condition, work to be performed shall be considered energized electrical work.
- This policy applies to all qualified electrical personnel.
- Overhead line work is not covered under this policy.
 Only an electrically qualified individual may perform energized work.

Personnel

ENERGIZED WORK JUSTIFICATION

Prior to performing energized work, an electrical risk assessment must be completed to determine if an energized work permit must be completed.

Exposed

Employees need to understand electrical exposure as part of the risk assessment in any task. With electrical equipment, most enclosures provide a barrier from energized conductors. Sites need to protect employees from inadvertently, accidently, unintentionally touching, or approaching nearer than a safe distance to electrical equipment. For example, working on smaller 480V panels where 480V disconnects or transformers may be placed in a panel with PLCs or other low voltage electronics.

Energized Work Permit Requirements

 Any Repair work while energized in the restricted approach boundary, including physical alteration of electrical

February – Electrical FRM





GENERAL INFORMATION

 This defines the minimum requirements that must be followed if work requires circuits of 50 volts or more to be energized. Electrical personnel include for example: electricians, instrument technicians, relay technicians, linemen, electrical engineers, electrical superintendents, and in some cases computer/communications technicians.
 This policy does and provide a superintendents and the policy does and provide a superintendents.

personnel.
Only electrically perform the wor proper safety eq minimum requir equipment and i current edition c
Refer to the Arc specific rules for

Process for PPE se 1. Prior to perform

assessment shal GE exists. The "Arc | This of this documen req

GENERAL INFORMATION

This technical supplement is intended to establish minimum requirements for electrical Arc Flash studies in all Freeport-McMoRan mining operations and plants in order to balance production requirements, distribution system reliability and troubleshooting, to protect equipment, and to define administrative safety controls to properly protect our people

Management Process

FCX will assign an Electrical Safety Lead to oversee compliance to this policy and manage a process that includes: tracking the completion of electrical studies, application of arc flash labels, and updating of drawings.

Electrical Safety Lead

The Electrical Safety Lead, in coordination with site leaders, is responsible for verifying and documenting that each site is in compliance with FCX-HS03 Electrical Safety Policy. This includes verification and documentation that each site has updated arc flash results, in compliance with Arc Flash Study requirements section, and updated arc flash labels, single line drawings and an electrical equipment database, as defined in this document.

RELEASE 07/2018 | VERSION 1

Assessment and Shock Protection Boundaries

Shock risk assessment is the process that identifies exposure

protective measure to use.

to the potential electrical shock hazards, estimates the

measures are required and determines the appropriate

The check was set on her adapted identified on limited

TECHNICAL SUPPLEMENT

ELECTRICAL SAFETY FCX-HS03 | ARC FLASH MANAGEMENT

potential severity of a shock injury, estimates the likelihood

of occurrence of this injury and then determines if protective

Arc Flash Study Requirements

Three Phase electrical equipment, rated greater than 240V (RMS-LL), such as switchboards, panel boards, industrial control panels, meter socket enclosures, switchgear, and motor control centers (MCC) that are in other than dwelling units and that are likely to require examination, adjustment, servicing, or maintenance while energized shall have an arc flash analysis performed. One of two methods below shall be used to obtain the arc flash incident energy.

Incident Energy Analysis Method
 Arc Flash PPE Category Method

Equipment rated equal to or less than 240V may be labeled as follows:

- 3-Phase equipment rated 240V may be labeled with an incident energy of 4.0cal/cm².
- 3-Phase equipment rated less than 240V:
- Fed by a transformer rated less than 125KVA, may be labeled with an incident energy of less than 1.2cal/cm²
 Fed by a transformer rated greater than or equal to
- 125KVA, may be labeled with an incident energy of

- Minimum requirements if work requires 50V or more to be energized - NFPA 70F
- Arc Flach Bour
- Arc Flash Boundary
- PPE based on the incident energy shown on arc flash label or from "Arc Flash Risk Assessment"
- Arc Flash Study Requirements

FCX-HS03 Electrical Personnel Protective Clothing Equipment Technical Supplement.pdf

FCX-HS03 Arc Flash Management Technical Supplement.pdf

February – Electrical FRM




- Requirements for allowing qualified, nonelectrical personnel to work safely when switching/operating designated electrical equipment

- Unless specifically trained, no disconnecting means rated greater than 300V

- Non-electricians trained may operate between 300V-1000V (Shall be labeled)

- Access to MCC to be only for "Qualified Electricians" unless discussions or other measures have been put in place and non-electrician have a specific task/need to be in MCC



<u>FCX-HS03 Switching for Non-Electrical Personnel Technical</u> <u>Supplement.pdf</u> Policy Interpretation Letter- Electrical Safety.pdf

February – Guarding/Entanglement



Guarding

Material handling systems components shall be guarded to prevent individuals from contacting moving machine parts. Guarding shall be readily identifiable as a guard and properly secured. They shall be maintained in a condition that is not easily defeated by intentional or accidental behavior of employees.

Sites must ensure all guarding and pull cords meet applicable regulations and requirements.

§ 56.14107 Moving machine parts.

- (a) Moving machine parts shall be guarded to protect persons from contacting gears, sprockets, chains, drive, head, tail, and takeup pulleys, flywheels, couplings, shafts, fan blades, and similar moving parts that can cause injury.
- (b) Guards shall not be required where the exposed moving parts are at least seven feet away from walking or working surfaces.

- Flagging/barricading
- Loose jewelry/Clothing/Hair
- Safe Distances
- Escape Routes
- LOTOTO Procedures
- Replacement of guards after maintenance work

Health & Safety Team 2025





FOREMOST IN CO

Health & Safety Team Assignments 2025

- Mine/IH/Admin oversight Dora Bleak, Sr. Supervisor 928 965-8637
 - Mine Ops Marjorie Ogas, H&S Specialist 928 965-1551
 - Mine Maintenance H&S Specialist
 - o Industrial Hygiene Kirk Redden, IH Lead 928 324-5348
 - o Admin Assistant Dolli Herrera 928 792-7273

Project/Processing oversight – Shannon Del Curto, Sr. Supervisor 928 379-9326

- Hydromet/Leaching Christie Stannard, H&S Lead 928 651-5582
- Crush Convey Franus Tomkiewicz, H&S Specialist 928 432-1309
- Projects Jennifer Cheatham, H&S Specialist
- Projects, Exploration, Rescue Joe Santiago 928 965-0231



You Are All Safety Pros!

Carefulness costs you nothing. Carelessness may cost you your life.

30

QUESTIONS, FEEDBACK, CONCERNS?





Attendees



32