



Monthly Contractor Safety Meeting

April 9, 2019



POWERED BY COPPER

Morenci Environmental Services

Environmental Share Dust Management

April 2019

<u>What:</u> Morenci's Title V Air Quality Permit requires that reasonable precautions are employed to prevent excessive dust from becoming airborne.

<u>Who:</u> All employees and contractors are required to help prevent dust from becoming airborne.

All areas of the mine, including:

- Blasts
- Conveyors
- Unpaved Roads, etc.



When: Any dust is occurring, take necessary action(s) to mitigate immediately.

How:

- Drive to the conditions of the road (15mph when dry/dusty conditions)
- Call for a water truck or water application
- Contact the control room operator and request water application or a water truck
- Manage piles of accumulated dust fines (vacuum or remove it)
- Call or notify Environmental Services Department





Questions? Or need more information call: Environmental Services 928-865-6000

		FREEPORT	McMoRan
		PFE #	PFE - 2018 - 3
	PUTENTIAL FATAL EVENT ADVISORY	IMS #	94759
<u> </u>		OPERATION:	Chino
		INCIDENT DATE:	1/26/2019
	Haul Truck and Somuco Truck	TIME:	11:30 a.m.
		TYPE:	Prop
	Collision		erty
			Dam
			age
		PFE Follow-Up:	

DESCRIPTION / DETAILS OF ADVISORY

Summary: A high-energy event occurred when a loaded haul truck rolled and stopped on top of an unoccupied service truck

after the haul truck had been manually started with air following brake work. Both vehicles caught on fire.

Description: A mine maintenance mechanic went to service a loaded haul truck with locked up brakes. Before starting work, a rubber tire dozer placed a dirt chocking berm in front of the driver side front tire. The mechanic then diagnosed the issue and went back to the warehouse for parts.

Later that morning, the mechanic returned to fix the brakes and parked the service truck in front of the

chocking berm / haul truck. After completing the job, the mechanic manually started the haul truck with air

and instructed the driver to put the gear in reverse to test the brakes. When the driver disengaged the

service brake, the truck began to roll forward.

The mechanic, who was about to turn off the air compressor, noticed the truck was rolling and ran out of the way.

The haul truck proceeded to roll over the chocking berm and stopped on top of the service vehicle. The haul truck's front bumper struck the air compressor, which caused the service truck and then the haul truck to catch on fire. The driver saw flames from under the cab, activated the fire suppression system and was able to safely dismount the truck. The mechanic's handheld radio was in the service truck – to call a Mayday, the employees ran 3/4 of a mile on the haul road until they found an employee with a radio.

Vehicle Impact to Person N/A			
OTHER SIGNFICANT RISK (specific to site or task not categorized as global)			
 Inadequate risk assessment to include the energy associated with a haul truck on a grade 			
ABSENT / INSUFFI	CIENT CONTROLS CONTRIBUTING TO THE EVENT		
Placement of chocking berm – the ber	rm was 5 feet in front of the tire, a distance that allowed the truck to		
Placement of chocking berm – the ber build up enough momentum to roll ov Placement and proximity of the servic Method for testing the brakes of a load Failure to move service truck from wo	rm was 5 feet in front of the tire, a distance that allowed the truck to the the berm e truck to the haul truck ded haul truck on a 9 percent downward grade rk area prior to operating the haul truck		
Placement of chocking berm – the ber build up enough momentum to roll ov Placement and proximity of the service Method for testing the brakes of a load Failure to move service truck from wor	rm was 5 feet in front of the tire, a distance that allowed the truck to the berm e truck to the haul truck ded haul truck on a 9 percent downward grade rk area prior to operating the haul truck CIES APPLICABLE STANDARDS / POLICIES /		





This is NOT an investigation report. It is a NOTIFICATION of a Significant advisory, event, occurrence, notice, regulatory action, or recall that requires immediate attention and action(s) at a Freeport-McMoRan operation and is being communicated to enhance safety awareness and information.

			PFE #	PFE - 2019 -
PC	TENTIAL FATAL EVEN	r Advisory	IMS #	95273
			OPERATION:	Miami
	Near Miss. Maltar Mat	to filled	INCIDENT DATE:	2/14/2019
	Near Miss – Molten Mat	te-med	TIME:	1552
	Ladle ar	nd Track	I YPE:	Near Miss
	Loader		TTETONOW-Op.	
Issued By: Brand	lon Gilley	Contact For Addi	ional Details: 928-701-7	7424
	DES	CRIPTION / DET	AILS OF ADVISOR	Y
				. -
Summary: A track	k loader operating inside the conve	erter alsle was struck	by a molten matte-f	filled ladle
being moved by t	he overhead crane.			
copper- bearing n began to move a crane towards the was spilled.	fourth ladle of molten matte for tra converter, the ladle struck the rig	ht upper corner of the	fame operator furthe converter. When bac he track loader. No m	buyin the als sking up the nolten materia
The crane operato	or immediately lowered the ladie to	o the ground and in	formed the track load	der operator, v
was unaware the	incident had occurred. The rear	end of the loader w	as facing the crane,	and the oper
did not feel the bu	imp due to the regular jerky mover	ments of the loader.		
	FAT	AL RISKS		
Contact with Mol	ten Material	Lifting Operation	s	
	OTHER SIGNFICANT RISK	(an a sifi a ta sita an		
		(specific to site or	task not categorized	das global)
N/A		c (specific to site or	task not categorized	d as global)
N/A	ABSENT / INSUFFICIENT C	CONTROLS CONT	task not categorized RIBUTING TO THI	d as global) E EVENT
 N/A Ineffective a for clearand relying on e 	ABSENT / INSUFFICIENT (dministrative control – The loader the to enter the converter aisle. How mployee communication to preven	CONTROLS CONT operator followed pr vever, this administr tt a dangerous inter	task not categorized RIBUTING TO THI ocedures to contact ative control was ine action.	ti as global) E EVENT the crane ope ffective by sole
 N/A Ineffective a for clearance relying on e Current processory 	ABSENT / INSUFFICIENT (dministrative control – The loader the to enter the converter aisle. How mployee communication to prever redures allow molten metal transfe As an immediate corrective action, when mobile equipment is working	CONTROLS CONT operator followed pr vever, this administr it a dangerous inter rs to occur while mo all ladle transfers o g in the converter ais	RIBUTING TO THI ocedures to contact ative control was ine action. abile equipment is op f molten matte have sle.	t as global) E EVENT the crane oper ffective by sole rerating in the been halted
N/A Ineffective a for clearance relying on e Current proc o HEALT	ABSENT / INSUFFICIENT (dministrative control – The loader the to enter the converter aisle. How mployee communication to prever evelures allow molten metal transfe As an immediate corrective action, when mobile equipment is working TH AND SAFETY POLICIES	CONTROLS CONT operator followed pr vever, this administr at a dangerous inter rs to occur while me all ladle transfers o g in the converter ais APPLIC.	RIBUTING TO THI ocedures to contact ative control was ine action. bbile equipment is op f molten matte have sle.	ti as global) E EVENT the crane oper ffective by sole rerating in the been halted
N/A Ineffective a for clearance relying on e Current proc o HEALT	ABSENT / INSUFFICIENT C dministrative control – The loader to enter the converter aisle. How mployee communication to preven edures allow molten metal transfe As an immediate corrective action, when mobile equipment is working	CONTROLS CONT operator followed pr vever, this administr at a dangerous inter rs to occur while mo all ladle transfers o g in the converter ais APPLIC	RIBUTING TO THI ocedures to contact ative control was ine action. bile equipment is op f molten matte have sle. ABLE STANDARDS	t as global) E EVENT the crane ope ffective by sole rerating in the been halted S / IES /
N/A Ineffective a for clearance relying on e Current proc O HEALT	ABSENT / INSUFFICIENT C dministrative control – The loader to enter the converter aisle. How mployee communication to preven edures allow molten metal transfe As an immediate corrective action, when mobile equipment is working TH AND SAFETY POLICIES	CONTROLS CONT operator followed pr vever, this administr at a dangerous inter rs to occur while mo all ladle transfers o g in the converter ais APPLIC.	RIBUTING TO THI ocedures to contact ative control was ine action. obile equipment is op f molten matte have sle. ABLE STANDARDS POLIC BDOCT	t as global) E EVENT the crane ope ffective by sol erating in the been halted S / IES /
N/A Ineffective a for clearance relying on e Current proce MEALT	ABSENT / INSUFFICIENT (dministrative control – The loader e to enter the converter aisle. How mployee communication to preven edures allow molten metal transfe As an immediate corrective action, when mobile equipment is working TH AND SAFETY POLICIES	CONTROLS CONT operator followed pr vever, this administr it a dangerous inter rs to occur while mo all ladie transfers o g in the converter ais APPLIC	RIBUTING TO THI ocedures to contact ative control was ine action. obile equipment is op f molten matte have sle. ABLE STANDARDS POLIC PROCI	t as global) E EVENT the crane oper ffective by sole rerating in the been halted S / IES / EDURES
N/A Ineffective a for clearance relying on e Current proce HEALT	ABSENT / INSUFFICIENT (dministrative control – The loader the to enter the converter aisle. How mployee communication to prever edures allow molten metal transfe As an immediate corrective action, when mobile equipment is working TH AND SAFETY POLICIES	CONTROLS CONT operator followed pr vever, this administr it a dangerous inter rs to occur while mo all ladle transfers o g in the converter ais APPLIC.	RIBUTING TO THI ocedures to contact ative control was ine action. bbile equipment is op f molten matte have sle. ABLE STANDARDS POLIC PROCI	t as global) E EVENT the crane ope ffective by solver erating in the been halted S / IES / EDURES



Circled in red is the ladle making contact with the track loader.

This is NOT an investigation report. It is a NOTIFICATION of a Significant advisory, event, occurrence, notice, regulatory action, or recall that requires immediate attention and action(s) at a Freeport-McMoRan operation and is being communicated to enhance safety awareness and information.

			FREEPO	T-McMoRAN
			PFE #	PFE – 2019 - 5
	POTENTIAL FATAL EVEN	I ADVISORY	IMS #	95437
			OPERATION:	Morenci
			INCIDENT DATE:	2/21/2019
	C Switchgear Electr	Switchgear Electric Shock	TIME:	4:30 p.m.
			TYPE:	Injury
			PFE Follow-Up:	
Issued By: Scott Brack		Contact For Addition	al Details: Rob Carte	r

DESCRIPTION / DETAILS OF ADVISORY

Summary: A contractor electrician sustained a hand injury after receiving an electric shock while

performing switchgear maintenance.

Description: A contractor electrician was at Metcalf SX to perform preventive 4160V switchgear maintenance. Prior to the start of the job, the Hydromet supervisor isolated two breakers to support the contractor's LOTOTO. The contractor electrician tested for zero energy and proceeded to clean the 4160V switchgear. About an hour later, the contractor electrician received an electric shock on the middle finger when it touched a stab in the switchgear. The stab had become energized after power was restored to the substation feeding the switchgear.

An initial investigation revealed that an unexpected outage on the feeding substation affected the validity of the "Try Out" performed by the contractor. In addition, one of the two switches that had been isolated during LOTOTO was incorrect.

FATAL RISKS

Contact with Electricity

N/A

OTHER SIGNFICANT RISK (specific to site or task not categorized as global)

N/A

ABSENT / INSUFFICIENT CONTROLS CONTRIBUTING TO THE EVENT

- Failure to properly perform LOTOTO specifically, incorrect breaker isolation and invalid "Try Out"
- Electrical prints and one-line drawings were not available in the field
- Failure to communicate the substation power restoration
- Failure to follow SOP requiring the use of ground clusters

HEALTH AND SAFETY POLICIES	APPLICABLE STANDARDS / POLICIES / PROCEDURES
Energy Control (LOTOTO)	

Rev: 2 March 2017



			PFE #	PFE - 2019 - 6
POTENTIAL FATAL EVENT ADVISORY		IMS #	95234	
\frown			OPERATION:	PTFI
			INCIDENT DATE:	2/13/2019
	Mobile Crane Co	ontact	TIME:	1:45 p.m.
	with Energized Overhead		TYPE:	Pro
				per
Power Line			ty	
			Da	
				ma
			PEE Follow-Lip:	ge
leaved Dur C		Contact For Addition	al Details: Ida Bague	Ardana Putra
Issued By: Geo	rge marges at <u>gmarges@fml.com</u>	at pibardan@fmi co	n	Aluana Futra
at pibardan@fmi.com				
ummary: A mo escription: A ewatering Plan ontact with an inucture. The e napped line can	DESC obile crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the g energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the o aterials in a nearby	ILS OF ADVISOF ower line during lif and move conve to rope of the crane he line to snap and crane into the grou bin, starting a fire.	ting operations. yor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera
cummary: A more the scription: A lewatering Plan ontact with an tructure. The empeded line can tepped out of the scription	DESC obile crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the gi energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m he cabin after seeing other employe	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the aterials in a nearby es running from the	ILS OF ADVISOF wwer line during lif and move conve prope of the crane he line to snap and crane into the grou bin, starting a fire. a area. Nobody wa	ting operations. yor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera is injured during t
cummary: A more rescription: A rewatering Plan ontact with an tructure. The e napped line can tepped out of the cident.	DESC obile crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the gr energized 2,400-volt overhead power electric current discharged through the ne in contact with wood and other m he cabin after seeing other employe	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the aterials in a nearby es running from the AL RISKS	ILS OF ADVISOF iower line during lif and move conve prope of the crane he line to snap and crane into the grou bin, starting a fire. a area. Nobody wa	ting operations. yor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera as injured during t
eummary: A mo escription: A bewatering Plan ontact with an tructure. The e napped line can tepped out of t icident.	DESC oblie crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the gr energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m he cabin after seeing other employe FAT/ ectricity	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire line. This caused t e outriggers of the aterials in a nearby es running from the ALRISKS Lifting Operations	ILS OF ADVISOF ower line during lif and move conve orope of the crane he line to snap and crane into the grou bin, starting a fire. e area. Nobody wa	ting operations. yor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera is injured during t
eummary: A more rescription: A lewatering Plan ontact with an tructure. The e napped line can tepped out of the cident.	DESC obile crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the gr energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m he cabin after seeing other employe FATA ectricity OTHER SIGNFICANT RISK (RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the e aterials in a nearby es running from the AL RISKS Lifting Operations (specific to site or t	ILS OF ADVISOF ower line during lif and move conve to pe of the crane he line to snap and crane into the grou bin, starting a fire.	ting operations. yor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera as injured during t d as global)
Pescription: A Newatering Plan ontact with an tructure. The e napped line can tepped out of the cident.	DESC obile crane came in contact with an er crane operator was using a 45-ton it. When lowering a used roll to the gi energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m he cabin after seeing other employe FATA ectricity OTHER SIGNFICANT RISK (ABSENT / INSUFFICIENT CO	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the e aterials in a nearby es running from the AL RISKS Lifting Operations (specific to site or t	ILS OF ADVISOF ower line during lif and move conve rope of the crane he line to snap and crane into the grou bin, starting a fire. a area. Nobody wa ask not categorize	Y ting operations. yor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera as injured during t d as global) E EVENT
eummary: A mo eescription: A lewatering Plai ontact with an tructure. The e inapped lout of the acident. Contact with El locident.	DESC obile crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the gr energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m he cabin after seeing other employe FATA ectricity OTHER SIGNFICANT RISK (ABSENT / INSUFFICIENT CC conduct proper spotting operation duri dentify fatal risks and use critical cont a pre-job planning to effectively mitiga	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the o aterials in a nearby les running from the AL RISKS Lifting Operations (specific to site or t DNTROLS CONTR ing lift trols. te risks.	ILS OF ADVISOF ower line during lif and move conve prope of the crane the line to snap and crane into the grou bin, starting a fire. a area. Nobody wa	Y ting operations. yor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera as injured during t d as global) E EVENT
Summary: A mo Description: A Dewatering Plan ontact with an tructure. The e napped line can tepped out of the acident. Contact with El Contact with El H/A Failure to a Failure to a Inadequate	DESC obile crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the gr energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m he cabin after seeing other employe FATA ectricity OTHER SIGNFICANT RISK (ABSENT / INSUFFICIENT CC conduct proper spotting operation duri dentify fatal risks and use critical cont a pre-job planning to effectively mitiga	RIPTION / DETA hergized overhead p mobile crane to liff round, the steel wirr r line. This caused t e outriggers of the o aterials in a nearby es running from the ALRISKS Lifting Operations (specific to site or t DNTROLS CONTR ing lift trols. te risks. APPLICA	ILS OF ADVISOF iower line during lif and move conve prope of the crane the line to snap and crane into the grou bin, starting a fire. a area. Nobody wa ask not categorize IBUTING TO TH BLE STANDARD	RY ting operations. yor belt rolls at t swung and came d energize the crain ind. Additionally, t The crane operations as injured during t d as global) E EVENT S /
Aummary: A more than the secret plane in the secret plane in the secret plane in the secret plane in the secret plane is the s	DESC oble crane came in contact with an er crane operator was using a 45-ton nt. When lowering a used roll to the gr energized 2,400-volt overhead power electric current discharged through the me in contact with wood and other m he cabin after seeing other employe FATA ectricity OTHER SIGNFICANT RISK (ABSENT / INSUFFICIENT CC conduct proper spotting operation duri dentify fatal risks and use critical cont a pre-job planning to effectively mitiga TH AND SAFETY POLICIES	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the o aterials in a nearby es running from the AL RISKS Lifting Operations (specific to site or t DNTROLS CONTR ing lift trols. te risks. APPLICA	ILS OF ADVISOF iower line during lif and move conve prope of the crane he line to snap and crane into the grou bin, starting a fire. a area. Nobody wa ask not categorize IBUTING TO TH BLE STANDARD POLIC	RY ting operations. tyor belt rolls at t swung and came d energize the craine ind. Additionally, t The crane operations as injured during t d as global) E EVENT S / LIES /
Summary: A mo Description: A Devatering Plan ontact with an tructure. The e napped line can tepped out of the acident. Contact with El Contact	DESC obile crane came in contact with an err crane operator was using a 45-ton it. When lowering a used roll to the gr energized 2,400-volt overhead power jectric current discharged through the me in contact with wood and other m he cabin after seeing other employe FAT/ ectricity OTHER SIGNFICANT RISK (ABSENT / INSUFFICIENT CC conduct proper spotting operation duri dentify fatal risks and use critical cont a pre-job planning to effectively mitiga TH AND SAFETY POLICIES	RIPTION / DETA hergized overhead p mobile crane to lift round, the steel wire r line. This caused t e outriggers of the e aterials in a nearby es running from the AL RISKS Lifting Operations (specific to site or t DNTROLS CONTR ing lift trols. the risks. APPLICA	ILS OF ADVISOF ower line during lif and move conve prope of the crane he line to snap and crane into the grou bin, starting a fire. a area. Nobody was ask not categorize IBUTING TO TH BLE STANDARD POLIC PROC	RY ting operations. tyor belt rolls at t swung and came d energize the cra ind. Additionally, t The crane opera as injured during t d as global) E EVENT S / CIES / EDURES

Rev: 2 March 2017



			FREEPORT-N	IcMoRan
	DOTENTIAL PATAL EVEN		PFE #	PFE – 2019 -
	PUTENTIAL FATAL EVENT ADVISORY		IMS #	<u>94924</u>
\frown			OPERATION:	PT RUCCI
			INCIDENT DATE:	2/2/2019
	Crush Injury betwe	een Two	TIME:	01:35
	Mohile		TYPE:	Injury
	MODILE		PFE Follow-Up:	
	Equip	nent Units		
ued By: Chris Zimmer – czimmer@fmi.com Contact For Additional		al Details: Daniel Simar	njuntak –	
		dsimanju@fmi.com		-
	DESCR	IPTION / DETAILS	OF ADVISORY	
operator stepp the same time to shift backw	bed between the two vehicles to secu e, the sprayer truck operator raised th	re the transfer chute the jacks on the shotcre	o the side of the mix ete sprayer. This cau	er truck. At used the unit
The sprayer tr Medical assis medical treatm underway.	varues, pinching the mixer operator bein uck operator immediately moved the stance was called and the mixer opera- nent. The employee sustained injurie	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs	s. ease the mixer opera o the hospital for furt s. An investigation is	ator. her
The sprayer tr Medical assis medical treatn underway.	varues, pinching the mixer operator being the	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs ALRISKS	s. ease the mixer opera o the hospital for furt s. An investigation is	ator. :her
The sprayer tr Medical assis medical treatm underway. Vehicle Impar	rards, pinching the mixer operator being the mixer operator being the mixer operator being the stance was called and the mixer operator being the mixer operator being the mixer operator being the stance was called and the stance	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs AL RISKS N/A	s. ease the mixer opera o the hospital for furt s. An investigation is	ator. her
The sprayer tr Medical assis medical treatm underway. Vehicle Impa	vards, pinching the mixer operator beil uck operator immediately moved the stance was called and the mixer opera nent. The employee sustained injurie FATA ct to Person OTHER SIGNFICANT RISK (s	ween the two vehicles vehicle forward to rele ator was transported to is to the ribs and lungs L RISKS N/A pecific to site or task	s. ease the mixer opera o the hospital for furt s. An investigation is not categorized as a	ator. her global)
The sprayer tr Medical assis medical treatm underway. Vehicle Impar	vards, pinching the mixer operator bei suck operator immediately moved the stance was called and the mixer opera nent. The employee sustained injurie FATA ct to Person OTHER SIGNFICANT RISK (s	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs LL RISKS N/A pecific to site or task	s. ease the mixer opera o the hospital for furt s. An investigation is not categorized as g	ator. :her global)
The sprayer tr Medical assis medical treatm underway. Vehicle Impar N/A	ards, pinching the mixer operator ben uck operator immediately moved the stance was called and the mixer opera- nent. The employee sustained injurie FATA ct to Person OTHER SIGNFICANT RISK (s ABSENT / INSUFFICIENT COM	ween the two vehicles vehicle forward to rele ator was transported to the ribs and lungs N/A pecific to site or task	s. ease the mixer opera o the hospital for furt s. An investigation is not categorized as g JTING TO THE EV	ator. ;her global) ENT
The sprayer tr Medical assis medical treatm underway. Vehicle Impar N/A N/A	ards, pinching the mixer operator beil uck operator immediately moved the stance was called and the mixer opera- nent. The employee sustained injurie FATA ct to Person OTHER SIGNFICANT RISK (s ABSENT / INSUFFICIENT CON truck operator entered a pinch point o move the cement mixer truck from e truck.	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs NL RISKS N/A pecific to site or task WTROLS CONTRIBU	s. ease the mixer opera o the hospital for furt s. An investigation is not categorized as g JTING TO THE EV raising the jacks on	ator. her global) ENT the
The sprayer tr Medical assis medical treatm underway. Vehicle Impar N/A • Cement • Failure t shotcret	ards, pinching the mixer operator being bein	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs NL RISKS N/A pecific to site or task VTROLS CONTRIBU the work area prior to APPLICABLE	s. ease the mixer opera o the hospital for furt s. An investigation is not categorized as a JTING TO THE EV raising the jacks on ESTANDARDS / P / PROCED	ator. iher global) ENT the OLICIES DURES
The sprayer tr Medical assis medical treatm underway. Vehicle Impar N/A • Cement • Failure t shotcret	ards, pinching the mixer operator being the mixer truck from the truck.	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs L RISKS N/A pecific to site or task VTROLS CONTRIBU the work area prior to APPLICABLI	s. ease the mixer operation to the hospital for furt s. An investigation is not categorized as a UTING TO THE EV raising the jacks on STANDARDS / P / PROCED	ator. her global) ENT the OLICIES DURES k)
The sprayer tr Medical assis medical treatm underway. Vehicle Impar N/A • Cement • Failure t shotcret HE/	ards, pinching the mixer operator being the cement mixer truck from the truck.	ween the two vehicles vehicle forward to rele ator was transported to as to the ribs and lungs L RISKS N/A pecific to site or task WTROLS CONTRIBU the work area prior to APPLICABLI	s. ease the mixer operation to the hospital for furt s. An investigation is not categorized as a UTING TO THE EV raising the jacks on STANDARDS / P / PROCED	ator. ther global) ENT the OLICIES DURES k)
The sprayer tr Medical assis medical treatm underway. Vehicle Impar N/A • Cement • Failure t shotcret HEZ	ards, pinching the mixer operator being the mixer truck from the truck.	ween the two vehicles vehicle forward to rele ator was transported to st to the ribs and lungs N/A pecific to site or task WTROLS CONTRIBU the work area prior to APPLICABLI • Maxi Jet (sh Operating F	s. ease the mixer opera o the hospital for furt s. An investigation is not categorized as a UTING TO THE EV raising the jacks on ESTANDARDS / P / PROCED	ator. her global) ENT the OLICIES DURES k)



Circled in red is the location of the employee when pinched between the concrete mixer truck (left) and shotcrete sprayer truck (right).

This is NOT an investigation report. It is a NOTIFICATION of a Significant advisory, event, occurrence, notice, regulatory action, or recall that requires immediate attention and action(s) at a Freeport-McMoRan operation and is being communicated to enhance safety awareness and information.

			Ev FREEPOR	T-McMoRan
		FICATION	Safety Alert #	SA – 2019 - 3
	SAFETY ALERT NUT	FICATION	IMS #	95104
			OPERATION:	Sierrita
	Sierrita Chlorine Release		INCIDENT DATE:	1/31/2019
		TIME:	5:30 a.m.	
			TYPE:	Near Miss
Issued By: Cath	y Fontes and Chris Viecelli	Contact For Additiona	al Details: Cathy Fon	tes

INCIDENT DESCRIPTION

Summary: Material incompatibility between a new titanium dump valve and dry chlorine resulted in a chlorine release and fire.

Description: Moly Processing was offloading the contents of the east railcar into chlorinator tank No.1. Approximately 20 minutes into the job, several chlorine sensors inside the Chlorinator Containment building indicated levels had exceeded 1 part per million (ppm). Shortly after, additional sensors inside the building indicated levels had exceeded 10 ppm. Around the same time, a fire ignited near the east railcar offloading station. These events triggered the building's automatic safety devices, and employees initiated the Emergency Action Plan. The building roll-up doors were closed and the railcar was isolated. The fire went out after about 20 seconds when the supply of chlorine was stopped.

An investigation revealed a new titanium dump valve had been installed on the east railcar unloading station

approximately two weeks before the incident. Designed for wet chlorine use, the titanium reacted violently with

the dry chlorine used at site.

FATAL RISKS	HEALTH AND SAFETY POLICIES
Exposure to Hazardous Substances – Acute	N/A

OTHER SIGNFICANT RISK (specific to site or task not categorized as global)

N/A

PROBABLE DIRECT CAUSES

 Material incompatibility – the titanium dump valve was designed for wet chlorine use and reacted violently to the dry chlorine (<1000 ppm water) used at site. Historically, lined cast-iron dump valves were used that required frequent replacement. To extend equipment life and reduce the risk of employee exposure to chlorine, valve vendor IPT Valves, Pumps and Services recommended switching to Titanium-body Flowserve Durco TSG4 valves.

IMMEDIATE CORRECTIVE ACTION(S)

- Initiated mayday.
- Blocked road adjacent to moly plant and closed main gate to all incoming traffic.
- Set up Cl₂ monitors outside the building and distributed handheld monitors to on-scene safety pros and ERRT members.
- Verified safety systems functioned inside chlorinator building, including auto car closer, auto valve

closure, scrubber start up, exhaust fan shutdown and sensor alarms. One roll-up door had to be

manually_activated.

REQUIRED ACTIONS(S)

- Implement practice to keep building roll-up doors closed with the exception of during rail car movements. Review incident with vendor who recommended the titanium valve. Change existing labels to read dry chlorine instead of chlorine. Review and update the Chlorine Emergency Response Plan. Complete and implement RCA actions. •
- •
- ٠
- •
- •







Railcar bay inside chlorinator building.



East railcar at the most intense period of the fire.



Damage to titanium dump valve.

This is NOT an investigation report. It is a NOTIFICATION of a Significant Incident that has taken place at a Freeport-McMoRan operation and is being communicated to enhance safety awareness should a similar situation exist. The information above is a preliminary assessment of the event and is not a formal investigation.

FREEPORT-MCMORAN

18

POWERED BY COPPER

Questions?

Thank you for attending!

Go Slow to Go Fast...

MARINA MARINA

(International International I