

September Contractor Safety Meeting

Cliff Mull and Timothy Liao

Safety Supervisors

November 12, 2019



PROVEN ASSETS.
FUNDAMENTAL VALUE.



Meeting Agenda



- Safety Share
- Emergency Exits/Meeting Point
- Cell Phones
- Facilities
- This months focus
 - Special Presentation Keats Jack from LVI Environmental Services Inc. (Northstar)
 - Branch Performance
 - Environmental Share
 - Hazardous Substance Management
 - Motorcycle Safety
 - Weekly Safety Audit Submissions
 - Recent Major Events
 - New Crane Policy in the works
 - On-boarding
 - Fatal Risk Patterns and Focuses
 - Contractor Monthly TRIR Report Reminder

Rain 4 Rent



Welcome Keats Jack Northstar

Environmental Share PCB Management



November 2019

- Polychlorinated Biphenyls (PCBs) are regulated under the Toxic Substance Control Act
- PCBs can cause harmful environmental and health effects
- PCB containers need to be properly labeled and stored
 - PCB containers are located at electrical shops and the Environmental Yard
- Oil-filled electrical equipment that may contain PCBs (BMP 309)
 - Transformers
 - Rectifiers
 - Capacitors
 - Light Ballasts



Questions? Or need more information call: Environmental Services (928) 865-6000







Contractors Health and Safety Manual



5.1 Hazardous Substance Management

- All hazardous substances, including chemicals require prior approval from the Health and Safety Department and environmental department before being brought to the project.
- The Contractor shall provide a list of all hazardous substances proposed for use for the services being performed along with the corresponding safety data sheet (SDS), the anticipated quantity, and the use and storage location. This shall be made available to FCX for approval purposes.

Contractors Health and Safety Manual



5.1 Hazardous Substance Management

- The list and respective SDS shall be updated on an ongoing basis -- substances previously not included in the initial submittal are subject to project approval and must undergo review before being brought onto the FCX property.
- Care shall be taken to select and use materials which can successfully accomplish the required work with minimal health or environmental impact.

Contractors Health and Safety Manual



5.1 Hazardous Substance Management

- All hazardous substances must be removed from the project within three days of completion of the work involving the substances, or within three days of completion of the contract, whichever occurs first.
- Contractors must maintain the most current SDS provided by manufacturers and distributors.
- Contractors must have an established Hazard Communication Program that meets all national, regional and local requirements.

Motorcycle Safety





You know who you are.....

Some Facts About Motorcycle Accidents



- 4,985 motorcyclists were killed in 2018
- 28% were drunk.
- AZ makes # 5 on states with most motorcycle fatalities per registration.
- Of all drunk induced fatal vehicle crashes, motorcyclists consisted the majority, followed by passenger cares, light trucks, and large trucks.



How to Stay Safe on a Motorcycle




- Before every ride, be sure to check tire pressure, tread path, brakes, lights, and fluid levels.
- The best hope you have in an event of a crash is wearing a helmet.
- Arms and legs should be completely covered.
- Wear gloves that give you the best grip, boots that cover your ankles, and brightly colored/reflective clothing.
- Ride sober
- Avoid riding in adverse weather conditions

Groups Submitting Weekly Audits



| | , pre- | | | | | |
|-----|--------|--------|--|--|--|--|
| | l Ca | ırrıer | | | | |
| 1 (| 1 5-0 | | | | | |



General Tool

Granite

___ Jays

Motion Industries

Sollers

WIRC

9/20/2019 7:30 AM File folder

10/1/2019 11:49 AM File folder

9/20/2019 1:40 PM File folder

5/16/2019 3:38 PM File folder

10/2/2019 7:12 AM File folder

7/2/2019 11:49 AM File folder

9/18/2019 7:09 AM File folder

7/9/2019 11:34 AM File folder

Potential Fatal Event



Western Copper Slope Failure

Potential Fatal Event Notification for a First Aid event that occurred at Morenci when a sudden slope failure engulfed a dozer that was cleaning a bench in Western Copper. The operator was able to be extracted from the equipment in under 20 minutes and received some minor scratches during that process. Controls on the equipment contributed directly to a reduction in the severity of injuries in the event.



Jump Starter Pack Explosions SA-2019 - 13

- Summary: The following Safety Alert provides information about ongoing investigations into two separate incidents where the same make and model jump starter pack exploded.
- **Description:** The company currently is conducting investigations into the following incidents at Morenci and Henderson operations involving jump starter packs that exploded, injuring employees.

Jump Starter Pack Explosions SA-2019 - 13

- Morenci: Two employees were attempting to jump-start a water truck in the asset recycling yard. They hooked up a Jump-N-Carry 12/24 volt jump starter pack set at 24 volts to the engine battery, but the truck did not start. The employees proceeded to hook up a second jump starter set at 12 volts and the engine turned over, but did not start. They then realized the voltage selection for the second starter was incorrect, so one employee disconnected the grounding cable and switched to 24 volts. Upon reconnecting the grounding cable, the second jump starter exploded resulting in injuries to the employee's right forearm and abdominal burns.
- An initial investigation revealed the cross voltage generated flammable gases within the plastic casing of the jump starter that ignited when the grounding cable was reconnected. The jump starter also did not have a warning system to alert of improper voltage selection.

Jump Starter Pack Explosions SA-2019 - 13


Henderson: A shop mechanic was repairing a rear-axle lift emergency stop control button that had come loose in the cab of a concrete transport truck. Once finished, the mechanic attempted to start the machine. It would not start so the mechanic assumed the battery charge was too low having been on for an extended period during repairs. The mechanic obtained a jump starter pack, connected the positive and ground leads, and began to plug the voltage selection cord into the 24-volt port on the jump starter when it exploded. The employee sustained injuries to the left hand and abdomen

Jump Starter Pack Explosions SA-2019 - 13

- Additional Equipment Information
- Material stock number: 40118783 (jump starter pack was same make/model at both sites)
- □ Clore Automotive Safety Manual:
- https://cloreautomotive.com/wpcontent/uploads/2018/08/JNC1224-Safety-Presentation.pdf
- Clore Automotive Operator's Manual:
- https://cloreautomotive.com/wp-content/uploads/2018/08/842-366-224.pdf



Jump Starter Pack Explosions SA-2019 - 13



Highlighted Incidents



Boom Contact with Power Line – SA-19-4

- INCIDENT DESCRIPTION
- Summary: An arc flash occurred when the raised boom of an excavator came in contact with an overhead power line.
- Description: A contractor employee was doing excavation work at the townsite tailings pond a location that required driving under overhead power lines. After working several hours, including under the power line, the employee switched to a larger excavator and drove under the power line with the boom raised. The boom made contact with the ground wire and pushed it up into a phase wire, causing an arc flash away from the excavator and tripping the breaker. No injuries or property damage occurred, and the excavator was not energized. Auto-reclosure on the breaker reengergized the line soon after the excavator passed.


Boom Contact with Power Line – SA-19-4



- FATAL RISKS HEALTH AND SAFETY POLICIES
- Exposure to Electrical Hazard
- N/A OTHER SIGNFICANT RISK (specific to site or task not categorized as global)
- N/A PROBABLE DIRECT CAUSES
- □ Failure to re-assess the job after equipment change
- Failure to lower boom and keep a safe clearance distance from the power line
- Absence of a spotter while operating heavy equipment under the overhead power line IMMEDIATE CORRECTIVE ACTION(S)



Boom Contact with Power Line – SA-19-4



Sierrita: Fork Lift Falls from Loading Dock



- Summary: A forklift fell 4 feet to ground level when a semitrailer moved during loading.
- **Description:** A forklift operator was entering a covered semitrailer from the loading dock when the semitrailer unexpectedly pulled forward. This created a gap between the dock and the trailer, resulting in the forklift falling 4 feet down to the ground level. The operator was able to independently step off the forklift, and employees in the area came over to the verify the operator was visibly unharmed. The job was stopped and supervision and safety notified. The forklift operator was medically evaluated and released back to full duty.



PROBABLE DIRECT CAUSES

- Inadequate assessment of risks and needs
- Inadequate guarding and barriers
- Failure to understood directions
- Failure to use identified controls (Loading Dock Locking system) to mitigate risks
- Inadequate department SOP for unloading does not include specifics for dock locking and semi driver procedures

IMMEDIATE CORRECTIVE ACTION(S)

- Stopped the job and notified supervision and safety
- Held a safety stand-down with entire department
- Shut down all incoming and outgoing shipments of moly concentrate until specific procedures were implemented
- Created a task specific SOP and ensured all employees are trained
- Advised transportation on updated procedures
- Re-established engineering controls (Loading Dock Locking System)

REQUIRED ACTION(S)

- Create safety communication (alert)
- Check RCA effectiveness





Morenci: Runaway Vac Truck



- **Summary**: An unmanned Vac Truck powered through the chocks during service and came within one foot of a mechanic walking in the area.
- **Description**: Two employees were operating a GapVax HV56 Vac Truck to perform routine work at the mill. The operator set the parking brake and exited the truck to check it was in the correct spot. The operator re-entered the truck, turned on the hydraulics and blower, then exited again to start work. There was no suction from the hose, so the operator asked the trainee to use the external control panel to rev up the RPMs to generate suction. When doing this, the truck powered through the chocks and proceeded down the alley unmanned. The trainee ran after the truck and was able to lower the RPMs using the external control panel to bring the truck to a stop. During the incident, the truck travelled 176 feet and came within one foot of a mechanic walking in the area. No injuries or property damage were sustained.

An initial investigation revealed the truck was not put in neutral gear before the parking brake was applied. In addition, the external control panel was found to be improperly wired, allowing power to be distributed to it.



PROBABLE DIRECT CAUSES

- Incorrect gear selection
- Incorrect parking procedure
- Lack of experience
- Improper wiring to the external control panel

IMMEDIATE CORRECTIVE ACTION(S)


- Notified supervision and safety
- Removed all Vac Trucks from service, including contractor equipment
- Pulled all employee training records / certifications and had OEM retrain employees
- Brought manufacturer onsite to provide information / training

REQUIRED ACTIONS(S)

- Created in-service inspection to ensure interlock is providing power to remote controls
- Now require all equipment with Power Take-Off (PTO) devices to meet inspection criteria before being put into service
- Improve Vac Truck training

Diagram of Situation





Safety Alert Notification: Property Damage



 Summary: A bi-annual, third-party inspection of lifting devices revealed visible cracks in two 6.5-ton bow shackles.

Description: A technician with Zurich Engineering was performing a bi-annual inspection* of lifting devices and discovered visible cracks in the bow section of two 6.5-ton bow shackles manufactured by Green Pin. Failure analysis by Exponent identified the cracks were caused by fatigue crack initiation and growth through cycle loading. The shackles were part of a fourleg chain sling attached to a lifting frame that hoists 11-ton crucibles. The frame is subjected to

approximately 24 – 36 lifting operations per day.





Crane Policy Feedback



FREEPORT-MCMORAN



POTENTIAL FATAL RISKS

Lifting Operations

CRITICAL CONTROLS

- · Barriers and Segregation
- Mechanical Integrity of Lifting Equipment
- . Lifting Execution

TRAINING REQUIREMENTS

General Awareness for all personnel working around cranes

Reference the Training Requirements Technical Supplement

ADDITIONAL RESOURCES?

ASME OSHA NCCCO

POLICY

OVERVIEW

This policy applies to all contractors and employees at all locations that utilize transcare digging equipment for the movement or adjusting of objects by holsting. Employees and contractors will not everk around or with cranes unless they are properly trained.

ACTIONS TO STAY SAFE

Supervisors will have the knowledge to advise crews on load limits of lifting devices.

Conduct and document inspections prior to use [rigging materials including: repes, chains, slings, ref.; and crame components including: outriggers, cables, blocks, hooks, etc.)

Conduct pre-task risk assessments and implement critical controls. Ensure and two-block devices are installed and functioning.

Always use softeners to protect slings from damage.

Crone operators will not engage in distracting activities.

Anyone can give the signal to stop operations.

No crane will be leaded beyond its capacity, or used for other than its

or signated purpose.
Ensure all moving parts are guarded if they expose employees to a hazard

Ensure all moving parts are guarded in they expose employees to a hazare Complete critical lift plans where necessary (see Technical Supplement). All crane activity will utilize redios on a designated channel.

Suspended Loads

- No one is permitted to ride the hook, ball or any portion of a load.
- No one will be a lowed under a suspended load unless it is effectively blocked from inadvertent movement.
- Use spotters, flagging or barricading to communicate the fall zone.
- Use push/pull sticks and tag lines whenever possible
- Guiding a load into place by hand is only permitted when employees:
 Have view of the height of the load
- o Understand potential plach points and trip hazards
- o Understand the potential and actual swing hazards
- o Not at risk of being struck should the load fall.
- o Maintain distance from the sling and load and between the sling and book

OPERATING STANDARDS/REQUIREMENTS/EXPECTATIONS

- The operator has final responsibility and control over the crane operations.
- Do not respond to unclear signals, or signals from anyone other than the designated signal person (with the exception of STOP).
- Never intentionally ignore signals.
- All loads will be attached to the hook with a sling or other approved device.
- Position the hook over the load to prevent load swing
- Properly seat rope in the drum and shoaves, ensuring line is not kinked or twisted (multiple part lines)

This printed supplement is an uncontrolled document. Vivil DOHS SharePoint site for current version and full policy details.

tliao@fmi.com

bwiley@fmi.com

cmull@fmi.com

On boarding



| | Contractor Contact Information Sheet (Provide to Safety Department) | | | | | | | | | |
|-----------------------------|---|---------|--------------------|------------------------|--------------|--------------|-------------|--|--|--|
| Company Name/ MSHA ID | | | | | | | | | | |
| | Street | | | City | | State | Zip Code | | | |
| Corporate Physical Address: | | | | | | | | | | |
| Corporate Mailing Address: | | | | | | | | | | |
| Project # | Contract # | | Type of Work | | Area Working | | FMI Contact | | | |
| Company MSHA TNG Plan | Yes 🗆 No 🗆 | | Approved instructo | r Name(s)/Organization | | Instructor's | MIN. Number | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | , | Corporate Contacts | | | <u>'</u> | | | | |
| Title | Name (First, MI, Last) | Phone # | Cell Phone# | E-mail Address | | | | | | |
| Owner/President | | | | | | | | | | |
| Safety Contact | | | | | | | | | | |
| Office Contact | | | | | | | | | | |
| | | | On Site Management | | | | | | | |
| Local Office Location(s) | | | on one management | | | | | | | |
| Title | Name (First, MI, Last) | Phone # | Cell Phone# | E-mail Address | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

What Do We Need to Focus On?



