

NEW MEXICO OPERATIONS - CHINO & TYRONE

HAZARD RECOGNITION

“Everything I Do Matters”



The following rules and guidelines apply during your visit at the Freeport-McMoRan New Mexico Operations. For your personal safety and the safety of others, observe these rules and guidelines at all times.

CONFIDENTIALITY AGREEMENT

While on the New Mexico Operations (Company) property, use of photographic or video equipment or similar technology is prohibited without the express prior written consent of Freeport-McMoRan. In consideration for the granting of permission to enter the Company property, I hereby agree all knowledge and information acquired or otherwise obtained by me relating to the site’s operations may not be used by me for any purpose or divulged to any person other than authorized representatives of the Company without the express prior written consent of Freeport-McMoRan.

RELEASE AND INDEMNITY

On behalf of myself, my parent and subsidiary corporations, in consideration for the granting of permission to enter upon the property owned by Company, I release and agree to hold harmless and indemnify Company, its affiliates, officers, employees, and agents, from and against all claims and all injuries, losses, and damages to any person or property arising out of entry onto Company’s operations from the date of this release.

HAZARD RECOGNITION AND AVOIDANCE

- Firearms, alcoholic beverages, drugs and narcotics are prohibited on Freeport-McMoRan New Mexico Operations (Company) property.
- All incidents regardless of severity must be reported promptly to security.
- Pets must remain in the vehicle.
- Stay clear of working mobile equipment as the operator may not see you.
- Smoking allowed only at designated smoking areas.
- Seatbelts must be worn by the operator and passengers when the vehicle is in motion.
- A two-way radio will be issued to drivers – gate personnel will advise on radio channel.
- Cell phone use by the driver of a moving vehicle is not permitted.

- An escort maybe provided depending on the site location and/or a drivers familiarity with the mine.
- Chino, Cobre and Tyrone mines observe left-hand traffic. Hurley observes right-hand traffic.
- Vehicle lights must be on for safety.
- Observe traffic and speed limit signs at all times.
- Unattended vehicles are required to be turned off, park brake set and chocked.
- Be alert for slip, trip and fall hazards.

BASIC PERSONAL PROTECTIVE EQUIPMENT – PPE

- Hard hat
- Safety glasses with side-shields – prescription glasses with side-shields
- Reflective Vest
- Safety toe boots with a defined heel
- Visitors may wear closed-toed shoes with prior approval.
- Long pants, sleeved shirt, Long sleeved shirt (in required areas)
- Gloves
- Additional PPE may be required within different departments. Contact area supervisor for additional information.

ADDITIONAL REQUIREMENTS FOR CATHODE TRUCK DRIVERS

Driver and passenger must remain in the cab when the truck is being loaded. No one is allowed to access the bed of the trailer at any time or for any reason. Each bundle must have two steel chains or fiber straps across it. The chains or straps must be applied and secured from the ground. Strap protectors mandatory. 5 MPH driving around SX buildings. Plan the load with the forklift operator. Use standard horn signals: One-Start, Two-Forward, Three-Reverse

CHINO SX PLANT

Drivers must have a confirmation release and shipment number from the SXEW Plant. At the east end of the north driveway, honk once to announce arrival. The flashing blue light indicates increased forklift traffic. Drive to the tie-down location and secure load. Return to the SX Scalehouse and scale out. Go inside Scalehouse to obtain BOL and paperwork. Drive back to the SX Security Gate and return all borrowed PPE and equipment.

TYRONE SX PLANT

At the SX plant, stop at the first STOP sign and wait for permission to drive to the loading area. If no one is present, sound the truck horn and wait for the forklift operator to arrive. Before driving to the loading area, stop at the second STOP sign and look for equipment and foot traffic in the area and at the bay door to your left. When loading is completed remove the wheel chocks and drive around the end of the building to the marked Tie-Down Area. After strapping the load, walk to the SX office located at the top of yellow stairs with these instructions and driver information sheet to collect paperwork. The road back to the front gate has a steep grade. Stop at the posted Brake Check Area and ensure the brakes are working properly before proceeding downhill. Follow the signs back to the front gate.

Weigh out at the front gate scale and then take all paperwork, radio and any other borrowed items into the security office.

There are no exceptions to these requirements. Failure to adhere to the requirements may result in not being loaded and not being allowed on the property.

PHONE NUMBERS

- Emergency Numbers
 - Internal
 - Chino/Cobre: 5911
 - Tyrone: 7222
 - External
 - Chino/Cobre/Tyrone: (575) 912-5911
 - Central Dispatch: 911
- Main Gates
 - Chino Mine: (575) 912-5655
 - Chino SX: (575) 912-5280
 - Hurley: (575) 912-5221
 - Cobre: (575) 912-5929
 - Tyrone: (575) 912-5886

FATAL RISKS PRESENT AT NEW MEXICO OPERATIONS

These symbols indicate a Fatal Risk may be present in the area. Please consult with local leadership before proceeding to ensure all Critical Controls are in place to prevent a serious incident from occurring.



Blasting



Confined Spaces



Drowning



Entanglement and Crushing



Exposure to Electrical Hazards



Fall from Heights



Falling Objects



Fire



Ground Failure



Hazardous Substance Acute Exposure



Hazardous Substance Chronic Exposure



Lifting Operations



Uncontrolled Release of Energy



Vehicle Impact on a Person



Vehicle Collision or Rollover



Rail Collision



Rail Impact on Person

LEGEND

- BUILDINGS
- STOCKPILES
- PITS
- MISC. AREAS
- PUBLIC ROADS
- TRUCK ROUTES
- SECURITY GATE
- ESCORT / LANDING ZONES
- ACID UNLOADING
- CATHODE LOADING
- FUEL DOCKS

