


Preliminary Incident Details

Operation	Henderson
Date / Time	March 22, 2024 / 8:20 a.m.
Event Type	Near Miss
Summary	Four contractor employees were working to align a belt system motor next to a gear box and break disk with removed guarding. The energy control coordinator (ECC) released the belt brake to initiate the lock out process which caused the belt to move one foot. Contractor employees recognized the system was not locked out and notified site supervision.
Risk Category	Actionable – Significant (3) Likely (3)
Findings / Missing Controls	<ul style="list-style-type: none"> • Lack of lock out, tag out, try out (LOTOTO) • Contractor missed ECC radio notification
Applicable Policies / Procedures	<ul style="list-style-type: none"> • Henderson Operations LOTOTO Program • FCX HS04 Control of Hazardous Energy
Employee Condition	No employees were injured.
Contact	Benjamin Goertz, Manager-Health & Safety

Photos / Links



Operations lock box. Contractor was locked on this box without the ECC lock.



Contractor work area