

Potential Fatal Event: Dozer backed into Light Vehicle

Preliminary Incident Details	
Operation	Morenci
Date / Time	September 6, 2023 / 4:05 p.m.
Туре	Injury
Summary	A dozer operator trainee was pushing material to maintain appropriate berm height at a dump. The support equipment lead and dozer mentor pulled up to the dump face in a light vehicle to inspect the berm height. The dozer operator trainee was about 65 feet away and started to back up. The support equipment lead noticed the trainee was headed towards the LV and not stopping. The lead tried to put the LV in reverse. The dozer trainee felt resistance while backing up and discovered they had contacted the LV.
Fatal Risk	Vehicle Collision and Roll Over
Risk Category	Actionable
Risk Rating	Significant (3) Likely (3)
Absent / Insufficient Controls	 Failed to make positive communication Approaching and parking in the blind spot of heavy equipment
Applicable Policies / Procedures	FCX – 23 Interaction with Heavy Mobile Equipment
Employee Condition	Minor abrasion to the left arm of the light vehicle operator
Contact	Haris (Kudir) Kudadiri, Manager-Fragmentation & Loading

Photos / Links



