

Potential Fatal Event: Manhaul Truck Collided with Crane



| Preliminary Incident Details | |
|--|--|
| Operation | PT Freeport Indonesia |
| Date / Time | December 4, 2023 / 11:30 a.m. |
| Туре | Injury |
| Summary | An Isuzu passenger transport truck was heading to Kasuang when the driver lost control along a steep downhill road segment. The vehicle hit a trash bin, causing it to spin, before striking a crane and coming to a stop. The trash bin struck a rigger who was standing nearby, resulting in injury. The truck operator's foot was pinched inside the cabin, requiring extraction to be released from the vehicle. |
| Fatal Risk | Vehicle Collision or Rollover |
| Risk Category | Actionable |
| Pre / Post Rating | Significant (3) Likely (3) |
| Findings / Missing Controls | Incorrect or unsuccessful use of proper gear selection Failure to operate vehicle according to road conditions Failure to secure control of the vehicle |
| Applicable Policies / Procedures | SOP-6.01-UGMO03 Operating Procedure Truck Isuzu NPS-75 Type Manhaul, Boom Crane and Rescue Truck in the Underground Mine and Surface Area |
| Employee Condition | Truck operator received first aid. Rigger sustained chest and hand injuries and is under observation. |
| Contact | Matthew Sullivan, Sr. Vice President-Underground Mine Division |

Photos / Links ISUZU loss control along steep road ISUZU avoid queuing vehicle in the traffic light waiting point ISUZU hit the corner of rorobin#1 and spin the rorobin before fully stopped after crashed into rear side of the crane Three indirect witness were Crane rigger was hit and thrown away working nearby crane into the ground by the spinning rorobin **ARD Portal**