

Type

Summary

Fatal Risk

Risk Category

Findings / Missing

Applicable Policies /

Employee Condition

Risk Rating

Controls

Procedures

Contact

Near Miss

Falling Objects

Medium

N/A

Safety Manager

been working moments earlier.

Significant (3), Possible (2)

· Flagging and Barricading

· Flagging and Barricading

• Drill Rig Pre-use Inspections

Manufacturer Specifications for Replacement

· Equipment Inspections

A contractor had successfully completed the drilling and construction of one of three test production wells southeast of Safford and was installing a gravel filter pack using a 3-inch tremie pipe. Throughout the process, there was clogging in the pipe. The

contractor lifted the pipe with a crane to clear debris when the main

cable snapped, causing a 100-pound steel ball to fall approximately

12 feet to the drilling platform below, where a driller and helper had

Michael Lacey, Manager-Hydrogeology. Bill Schneider, Health &

FREEPORT- MCMORAN

PFE # 2023 - 45

Event ID # 20012538

*	Potential Fatal Event: Drill Rig Cable Failed	
	Preliminary Incident Details	Photos / Link
Operation	Whitlock Valley Test Well-Land and Water	
Date / Time	December 28, 2023 / 6:10 a.m.	

The drill rig cables used during the pipe installation process.



Circled in red is the 100-pound steel ball that fell 13 feet to the drilling platform where two contractor employees had been working.