

**BAGDAD**  
HAZARD RECOGNITION



**The following rules and guidelines apply during your visit at Bagdad operations. For your personal safety and the safety of others, observe these rules and guidelines at all times.**

**CONFIDENTIALITY AGREEMENT**

While on Bagdad property, use of photographic or video equipment or similar technology is prohibited without the express prior written consent of Freeport-McMoRan. In consideration for the granting of permission to enter the Bagdad property, I hereby agree all knowledge and information acquired or otherwise obtained by me relating to the site's operations may not be used by me for any purpose or divulged to any person other than authorized representatives of Bagdad operations without the express prior written consent of Freeport-McMoRan.

**RELEASE AND INDEMNITY**

On behalf of myself, my parent and subsidiary corporations, in consideration for the granting of permission to enter upon the property owned by Freeport-McMoRan Bagdad operations, I release and agree to hold harmless and indemnify Freeport-McMoRan, its affiliates, officers, employees, and agents, from and against all claims and all injuries, losses, and damages to any person or property arising out of entry onto the company's operations from the date of this release.

**HAZARD RECOGNITION AND AVOIDANCE**

- **LEFT-HAND TRAFFIC** is used throughout the Bagdad property.
- The maximum speed on our property is **35 mph** unless otherwise posted. This is strictly enforced and violators will be cited. Repeat violators will lose their driving privileges on this property.
- Mobile equipment, including large machinery, always have the right of way. Do not drive or walk in front of or get too close to running machinery.
- Passing of mobile equipment is prohibited. Operator must pull off to the side and stop before you may pass.
- Everyone in a vehicle must wear a seat belt at all times.
- Headlights on vehicles are required to be ON at all times.
- Observe traffic regulatory signs and rules at all times.
- Honking Procedure: Before backing up, sound the vehicle horn three times. Ensure nothing is behind your vehicle. Two times for forward driving. One honk before starting engine.
- One-ton vehicles or larger must be chocked and have the park brake set when parked.

- Pets must remain in the vehicle, secured, and cannot be taken out of vehicle at any time.
- Observe all No Smoking areas.
- Passengers must be 18 years of age or older and must remain inside the vehicle at all times unless they are a licensed co-driver.
- Use proper eye protection in areas where cutting and welding work is being performed.
- Watch for overhead cranes in operation. Cranes in motion will have audible and visual alarms. Do not walk under suspended loads.
- Be alert for slip, trip and fall hazards.
- All vehicles are subject to periodic, unannounced inspections at any location on the site.
- Do not stop your vehicle to sightsee, collect rocks, etc. Proceed directly to your area of business and return via the same route.
- Do not enter any buildings unless you are authorized to do so.
- Freeport-McMoRan prohibits the transport or use of alcoholic beverages, drugs and narcotics on company property.
- Firearms are prohibited on mine property. Lockers are available at the main gate to store firearms before entering the site.
- All chemicals must be approved for use on site.
- Safety showers and eyewash stations are located throughout the site. In the event you are exposed to a hazardous chemical or substance, initiate a MAYDAY or call 928-633-5000, then proceed to the nearest safety shower. Flush with water immediately for a minimum of 15 minutes.

**MINE OPERATIONS (PIT)**

- Training and pit driving certification is required to drive on haul roads.
- A two-way radio with the "Pit Main" frequency and a buggy whip are required for all vehicles and equipment entering Pit haul roads. Buggy whips must be a minimum of 12 feet and have some form of working light at all times.
- Do not walk on, handle, or run over any electrical cables.

**BASIC PERSONAL PROTECTIVE EQUIPMENT – PPE**

- Hard hat
- Safety vest
- Safety glasses with side shields
- Closed toe shoes
- Long pants
- Additional PPE requirements may include: Hearing protection, fitted respirator, goggles and/or face shield, safety toe boots, chemical resistant suit

**MINE EMERGENCY**

**Initiate a Mine Emergency via:**

- RADIO by calling "MAYDAY, MAYDAY, MAYDAY" three times on the main channel in the area you are in
- RADIO by pushing the ORANGE button on handheld radio OR P4 button on mobile radio
- PHONE by calling **928-633-5000**

*Be prepared to identify the location and nature of the emergency, your name and whether an escort is available to meet the Emergency Responders, if necessary. It is imperative that you stay on the radio or phone with Security until told otherwise.*

**Report immediately any:**

- Injury, illness, property damage or unsafe condition.
- Spill of hazardous chemical or substance.

**FATAL RISKS PRESENT AT BAGDAD**

These symbols indicate a Fatal Risk may be present in the area. Please consult with local leadership before proceeding to ensure all Critical Controls are in place to prevent any serious incidents from occurring.



Blasting



Confined Spaces



Drowning



Entanglement and Crushing



Exposure to Electrical Hazards



Fall from Heights



Falling Objects



Fire



Ground Failure



Hazardous Substance – Acute Exposure



Hazardous Substance – Chronic Exposure



Interaction with Aircraft



Lifting Operations



Uncontrolled Release of Energy



Vehicle Impact on Person



Vehicle Collision or Rollover

**FM BAGDAD SECURITY**

*Achieve · Represent · Safeguard · Respect*  
**Main Gate Non-Emergency: 928-633-3211**  
**Mine Emergency: 928-633-5000**  
**Townsite Emergency: 911**


# Bagdad Mine: Site Delivery Locations

- ACCESS ROADS
- HAUL TRUCK ROADS (Restricted Access)

## Posted Signage

- ◆ CLP
- ▲ SX/EW
- WH41/Mine Shop
- WH42/Mill
- ★ Security Gate

- Remember Left-Hand Drive in Mine
- Cell Phone Use Prohibited While Operating a Vehicle
- Follow Gold Stars to Return to Security Gate



N  
\*Not Drawn to Scale