



Potential Fatal Event: SVS Mixer Contacts Light Vehicle

Preliminary Incident Details

| | |
|---|---|
| Operation | PT Freeport Indonesia |
| Date / Time | September 12, 2023 / 2:25 p.m. |
| Type | Property Damage |
| Summary | A light vehicle was traveling along a drift to the crane bay shop and came up behind an SVS mixer that was stopped behind a line of vehicles blocked by a Jumbo drill. The LV along with other vehicles began to reverse to seek alternative access. The LV stopped when the truck behind it stopped, but the SVS mixer kept reversing. The LV driver sounded the horn. The SVS mixer continued to reverse and contacted the LV, pushing it into the rib. The front left tire burst, damaging the front end and hood. No one was injured. |
| Fatal Risk | Vehicle Collision or Rollover |
| Risk Category | Actionable |
| Pre / Post Rating | Significant (3) Likely (3) |
| Findings / Missing Controls | <ul style="list-style-type: none"> • Failure to initiate correct action – SVS mixer lost visual of the LV and continued to reverse • Competing sounds made the LV horn inaudible |
| Applicable Policies / Procedures | <ul style="list-style-type: none"> • Mobile Equipment Interaction • SOP UM.2.18.GBC.SVS-MTO.02.03/19 SVS Mixer Truck Operating Procedure • SOP-4.04-PTFI-002 Light Vehicle Operation |
| Employee Condition | No Injury |
| Contact | Andri Abdullah or Phillip Murphy |

Photos / Links

