

Waste Management

Significant Risk - Changes in process cause loss of Bevill Exemption as applied to RCRA.

Potential Consequence - With loss of Bevill Exemption, comingling of regulated and non-regulated waste streams with processing, stockpile and tailings can result in an environmental and/or regulatory impact.

Controls We Use

Documents we follow:

- BMP 300 Series
- BMP 900—Management of Change Process

Engineering controls we use:

- Facility Design & Process Engineering

Monitoring, Inspections and Maintenance we conduct:

- Periodic Area Inspections
- Ongoing legal review of requirements
- Sampling and analysis of waste material

Training we receive:

- On the job training
- Annual Environmental Training
- Tailgate and/or other meetings
- New hire and/or site specific training
- Work instruction training
- Environmental Department Waste Management Training
- Supervisor Bootcamp Training