



Vehicle Collision

Actionable Event: Forklift and Truck Collision

Preliminary Incident Details

Operation	El Paso
Date / Time	March 22, 2024 / 1:32 p.m.
Event Type	Property Damage
Summary	A forklift operator was weighing a cathode bundle at the scale. When complete, the operator reversed and struck a travelling pickup truck. Both operators failed to look in the direction of travel and identify other mobile equipment in the area. Both continued work without stopping.
Risk Category	Actionable – Significant (3) Likely (3)
Findings / Missing Controls	<ul style="list-style-type: none"> • Failure to make eye contact with equipment operators • Failure to yield to moving equipment • Failure to look in direction of travel • Failure to utilize horn signals for movement notification
Applicable Policies / Procedures	<ul style="list-style-type: none"> • SAF-0220 Powered industrial equipment operations
Employee Condition	No employees were injured.
Contact	Roland Ruybe, Manager-Health & Safety

Photos / Links



Position of forklift and truck upon collision.