



Falling Objects

Actionable Event: H-Beams Fall from Trailer during Transport

Preliminary Incident Details

Operation	PTFI
Date / Time	February 16, 2024 / 2:15 p.m.
Event Type	Near Miss
Summary	During transportation, two steel H-beams, and six purlins fell from a trailer and slid approximately 320 meters passing two LVs and one Bus. The steel was tied with a cargo strap to the flat track. The truck operator immediately parked and notified a supervisor.
Risk Category	Actionable – Significant (3) Likely (3)
Findings / Missing Controls	<ul style="list-style-type: none"> • Site lacking loadmaster • Maintenance road crews not present
Applicable Policies / Procedures	<ul style="list-style-type: none"> • Material Mobilization Checklist (MOC) • KPI-CTR-011: Truck Operation of Flatbed, Trailer, & Lowboy
Employee Condition	No personnel were injured.
Contact	Harriadi Rasidi, Project Safety Manager Mill Optimization Construction (MOC)

Photos / Links

