





Vehicle Impact
to Person

Potential Fatal Event: Lowboy Runs Over Employee's Foot

Preliminary Incident Details	
Operation	PTFI Technical Services – Maintenance Support Division
Date / Time	May 29, 2024 / 7:59 a.m.
Event Type	Injury – Medical Treatment
Summary	A lowboy was moving out of the trailer shop at 5km/h (3 mph) with a spotter on the right side. Another employee approached the moving equipment from the left side to move a welding screen that had potential to be hit. The employee was positioned facing the welding screen. The left rear tire of the lowboy ran over the employee's right foot, resulting in major leg and foot injuries.
Risk Category	Actionable – Significant (3) Likely (3)
Findings / Missing Controls	<ul style="list-style-type: none"> • Failure to maintain safe distance from moving vehicles. • Failure to maintain safe visibility (victim unseen by spotter). • Failure to maintain positive communication between operator, spotter and offsideers.
Applicable Policies / Procedures	<ul style="list-style-type: none"> • Site standard operating procedure 4.04.10-KPI-MTCLL-32TRL-011, Entering and Exiting Unit
Employee Condition	<ul style="list-style-type: none"> • Employee sustained a crushing injury to the right foot and multiple fractures below the knee. • Employee is under medical observation.
Contact	<ul style="list-style-type: none"> • Lucky Hermawan, Vice President-Maintenance Support Division

Photos / Links	
 <p>• Incident reenactment. Position of employee to moving equipment.</p>	 <p>• Incident reenactment. Position of employee's right foot and the welding screen. The lowboy was moving 5km/h (3 mph).</p>