

Potential Fatal Event: Haul Truck to Light Vehicle Collision

Operation Morenci Date / Time June 11, 2023 / 11 p.m. Type Property Damage A light vehicle operator was leaving the dump and stopped behind a haul truck (A) that was stopped behind a piece of support equipment. The operator noticed another haul truck (B) was approaching from the rear at a high rate of speed. The operator was able to move the light vehicle far enough left toward the berm to keep the driver side out of the line of fire. Haul truck B proceeded to run over the light vehicle truck bed and passenger side cab, then into the back of haul truck A. The three operators received medical evaluations with no injuries. The ROPS system and High Performance (HP) truck bed was effective in protecting the operator of haul truck A. Fatal Risk Vehicle Collision or Rollover Risk Category Actionable Pre / Post Rating Significant (3) Likely (3) / Significant (3) Possible (2) Findings / Missing Controls Fit for Duty Applicable Policies / Procedures Haul Truck Operator Manual Employee Condition No injury Contact Cheikh Mohamed Saleh, Manager-Haulage			
Date / Time June 11, 2023 / 11 p.m. Property Damage A light vehicle operator was leaving the dump and stopped behind a haul truck (A) that was stopped behind a piece of support equipment. The operator noticed another haul truck (B) was approaching from the rear at a high rate of speed. The operator was able to move the light vehicle far enough left toward the berm to keep the driver side out of the line of fire. Haul truck B proceeded to run over the light vehicle truck bed and passenger side cab, then into the back of haul truck A. The three operators received medical evaluations with no injuries. The ROPS system and High Performance (HP) truck bed was effective in protecting the operator of haul truck A. Fatal Risk Vehicle Collision or Rollover Risk Category Actionable Pre / Post Rating Significant (3) Likely (3) / Significant (3) Possible (2) Findings / Missing Controls Applicable Policies / Procedures Haul Truck Operator Manual Employee Condition No injury	Preliminary Incident Details		
Type Property Damage A light vehicle operator was leaving the dump and stopped behind a haul truck (A) that was stopped behind a piece of support equipment. The operator noticed another haul truck (B) was approaching from the rear at a high rate of speed. The operator was able to move the light vehicle far enough left toward the berm to keep the driver side out of the line of fire. Haul truck B proceeded to run over the light vehicle truck bed and passenger side cab, then into the back of haul truck A. The three operators received medical evaluations with no injuries. The ROPS system and High Performance (HP) truck bed was effective in protecting the operator of haul truck A. Fatal Risk Vehicle Collision or Rollover Risk Category Actionable Pre / Post Rating Significant (3) Likely (3) / Significant (3) Possible (2) Findings / Missing Controls Fit for Duty Applicable Policies / Procedures No injury	Operation	Morenci	
A light vehicle operator was leaving the dump and stopped behind a haul truck (A) that was stopped behind a piece of support equipment. The operator noticed another haul truck (B) was approaching from the rear at a high rate of speed. The operator was able to move the light vehicle far enough left toward the berm to keep the driver side out of the line of fire. Haul truck B proceeded to run over the light vehicle truck bed and passenger side cab, then into the back of haul truck A. The three operators received medical evaluations with no injuries. The ROPS system and High Performance (HP) truck bed was effective in protecting the operator of haul truck A. Fatal Risk Vehicle Collision or Rollover Risk Category Actionable Pre / Post Rating Significant (3) Likely (3) / Significant (3) Possible (2) Findings / Missing Controls Fit for Duty Haul Truck Operator Manual No injury	Date / Time	June 11, 2023 / 11 p.m.	
haul truck (A) that was stopped behind a piece of support equipment. The operator noticed another haul truck (B) was approaching from the rear at a high rate of speed. The operator was able to move the light vehicle far enough left toward the berm to keep the driver side out of the line of fire. Haul truck B proceeded to run over the light vehicle truck bed and passenger side cab, then into the back of haul truck A. The three operators received medical evaluations with no injuries. The ROPS system and High Performance (HP) truck bed was effective in protecting the operator of haul truck A. Fatal Risk Vehicle Collision or Rollover Risk Category Actionable Pre / Post Rating Significant (3) Likely (3) / Significant (3) Possible (2) Findings / Missing Controls Fit for Duty Applicable Policies / Procedures No injury	Туре	Property Damage	
Risk Category Actionable Pre / Post Rating Significant (3) Likely (3) / Significant (3) Possible (2) Findings / Missing Controls Fit for Duty Applicable Policies / Procedures Haul Truck Operator Manual Employee Condition No injury	Summary	haul truck (A) that was stopped behind a piece of support equipment. The operator noticed another haul truck (B) was approaching from the rear at a high rate of speed. The operator was able to move the light vehicle far enough left toward the berm to keep the driver side out of the line of fire. Haul truck B proceeded to run over the light vehicle truck bed and passenger side cab, then into the back of haul truck A. The three operators received medical evaluations with no injuries. The ROPS system and High Performance (HP) truck bed was	
Pre / Post Rating Significant (3) Likely (3) / Significant (3) Possible (2) Findings / Missing Controls Fit for Duty Applicable Policies / Procedures Haul Truck Operator Manual Employee Condition No injury	Fatal Risk	Vehicle Collision or Rollover	
Findings / Missing Controls Applicable Policies / Procedures Haul Truck Operator Manual Employee Condition No injury	Risk Category	Actionable	
Applicable Policies / Procedures Haul Truck Operator Manual Employee Condition No injury	Pre / Post Rating	Significant (3) Likely (3) / Significant (3) Possible (2)	
Procedures Haul Truck Operator Manual Employee Condition No injury		Fit for Duty	
	- ·	Haul Truck Operator Manual	
Contact Cheikh Mohamed Saleh, Manager-Haulage	Employee Condition	No injury	
	Contact	Cheikh Mohamed Saleh, Manager-Haulage	

Photos / Links









Potential Fatal Event Learnings: Haul Truck to Light Vehicle Collision



Causal Factors

Haul truck driver was incapable of safely operating the truck due to being unfit for duty.

Action Items	Hierarchy of Controls
Stress to all personnel the critical importance of being fit for duty, including being free of drugs and alcohol, and that it is everyone's responsibility to speak up with any concerns about an individual who may appear to be unfit.	Administrative
Implement additional options for drug and alcohol testing out in the field during the work shift	Administrative

Additional Learnings / Opportunities

N/A

Fatal Risk Management Controls

Operating Competency – Sufficient

Fit For Work and Fatigue Management – Insufficient

 Am I fit for duty (compliant with drug and alcohol policy, well rested and free from fatigue, free from stressful work related or personal concerns that could potentially distract me from working safely)?

Vehicle Preoperational Inspection – Sufficient

• Have I conducted a pre-operational inspection prior to use.

Positive Communication System – Sufficient

Access Control - Sufficient

Segregation - Sufficient

Signage and Demarcation – Sufficient

Road Design And Maintenance – Sufficient