

## Potential Fatal Event: Employee Struck by Light Vehicle



Preliminary Incident Details	
Operation	El Abra
Date / Time	September 3, 2023 / 3:30 p.m.
Туре	Injury
Summary	Two employees were working at night to install an aeration system. They parked their light duty truck in the piping area, which was beyond the designated parking zone. During the job, one of the employees got back in the truck and drove in reverse to leave, striking another employee who was behind the truck. Emergency protocol was activated. The injured employee sustained multiple fractures.
Fatal Risk	Vehicle Impact to Person
Risk Category	Monitor
Pre / Post Rating	Significant (3) Possible (2)
Findings / Missing Controls	<ul> <li>Poor visibility due to glare from light plant on nearby facility</li> <li>No signage prohibiting parking beyond designated area</li> <li>Aftermarket engineering controls were not working properly (i.e., proximity sensor, backup alarm, backup camera)</li> </ul>
Applicable Policies / Procedures	Interaction with Heavy Mobile Equipment - Surface
Employee Condition	Recovering and in stable condition
Contact	Jaime Choque, jchoquer@fmi.com, +56-55-281-8645

## **Photos / Links**



Position of injured employee